



PORSCHE

Paul Miller Porsche

3419 US46

Parsippany, New Jersey, 07054, US

Phone: 9732273000

Repair Order #: 124476

Tag #: T5234

Advisor: Mike Rose

Advisor No. #: 45

Order Open Date: 2023-08-07

Customer Information

Vehicle Information

1995 PORS 911

VIN #: WPOCA2996SS341773

Color #:

Mileage In/Out #: 93525/93531

Job # A

Labor Total: \$ 0.00

PERFORM COMPLIMENTARY BRAKE, BATTERY AND TIRE INSPECTION AS PER ATTACHED SHEET.

Cause:

Correction(s):

MPI PERFORM COMPLIMENTARY BRAKE, BATTERY AND TIRE INSPECTION AS PER ATTACHED SHEET.

\$0.00

Tech Number: 29 Labor Type: CPP

Part Number	Part Description	Qty	List
Parts Total: \$ 0.00			
Misc Total: No Charge			

Job # A Total \$ 0.00

Job # B

Labor Total: \$ 840.00

Annual service,

Cause:

Correction(s):

ANNUAL CUSTOMER REQUESTS PERFORM ANNUAL SERVICE (CLEAR WATER DRAINS, COWLS AND RADIATOR OF ALL DEBRIS WHERE APPLICABLE)

\$840.00

Tech Number: 29 Labor Type: GPPM

Part Number	Part Description	Qty	List
Parts Total: \$ 334.29			
993-107-203-05	OIL FILTER	1	\$ 43.68
993-207-201-03	OIL FILTER	1	\$ 37.74
999-701-269-40	O-RING	1	\$ 20.91
900-123-011-20	SEALING RING	2	\$ 4.65
PCG-043-210-15	ENGINE OIL	2	\$ 111.33

93528 ANNUAL SERVICE- PERFORMED SYNTHETIC OIL AND FILTER CHANGE/DRAIN PLUG. CLEARED WATER DRAINS, COWLS AND

* OEM means Original Equipment Manufacturer (factory) Parts | ** All parts are New unless specified otherwise.



PORSCHE

Paul Miller Porsche

3419 US46

Parsippany, New Jersey, 07054, US

Phone: 9732273000

Repair Order #: 124476

Tag #: T5234

Advisor: Mike Rose

Advisor No. #: 45

Order Open Date: 2023-08-07

RADIATOR OF ALL DEBRIS, TOPPED OFF VITAL FLUIDS, ADJUSTED TIRE PRESSURES AND PERFORMED COMPLETE SAFETY CHECK AND ROAD TESTED. READ OUT OF FAULT MEMORY-RESET OF SERVICE INTERVAL INDICATOR

Misc Total: No Charge

Job # B Total \$ 1,174.29

Job # C Labor Total: \$ 784.80

CUSTOMER STATES FOG LIGHTS DONT TURN ON

Cause:

Correction(s):

C REPLACE FOG LIGHT RELAY, FIX WIRING FOR LID LIGHTS \$784.80

Tech Number: 29 Labor Type: CPP

Part Number	Part Description	Qty	List		Parts Total: \$ 50.70
900-631-106-90	BULB	1	\$ 7.48	\$ 7.48	
141-951-253-B	RELAY	1	\$ 43.22	\$ 43.22	

93525 check fuse & relay, reverse lights work. r&i l/f fog lamp & found no + to assembly. need to trace out wiring. trace wiring as per diagram. found 1 of 3 relays missing. ordered & replaced relay.

Misc Total: No Charge

Job # C Total \$ 835.50

Job # D Labor Total: \$ 1,864.20

CUSTOMER STATES DEFROSTER IS NOT WORKING. CHECK ENTIRE AC SYSTEM

Cause:

Correction(s):

C REPLACE AC DRAYER AND FILL PORT \$1,864.20

Tech Number: 29 Labor Type: CPP

Part Number	Part Description	Qty	List		Parts Total: \$ 360.99
944-573-143-01	DESICCATOR	1	\$ 146.81	\$ 146.81	
999-707-262-40	O-RING	2	\$ 14.46	\$ 28.92	
R134A	FREON	2	\$ 29.42	\$ 58.84	
996-573-465-00	VALVE	1	\$ 52.64	\$ 52.64	

* OEM means Original Equipment Manufacturer (factory) Parts | ** All parts are New unless specified otherwise.



PORSCHE

Paul Miller Porsche

3419 US46

Parsippany, New Jersey, 07054, US

Phone: 9732273000

Repair Order #: 124476

Tag #: T5234

Advisor: Mike Rose

Advisor No. #: 45

Order Open Date: 2023-08-07

928-573-466-00	VALVE	1	\$ 53.78	\$ 53.78
FREIGHT	WARR FREIGHT	1	\$ 20.00	\$ 20.00

93528 recover .1 lb refrigerant. charge system, remove l/s wheels & liners, & check for leaks. when disconnecting charging station hoses, could see bubbling at both charge ports. reconnect & remove refrigerant. replaced "sop" receiver/drier & hi & lo pressure charge ports. evacuate, leak test, & charge system.

Misc Total: No Charge

Job # D Total \$ 2,225.19

Job # E Labor Total: \$ 508.80

3RD BRAKE LIGHT BULBS

Cause:

Correction(s):

C REPLACE 3RD BRAKE LIGHT BULBS

\$508.80

Tech Number: 29 Labor Type: CPP

Part Number	Part Description	Qty	List	
999-631-135-91	BULB	3	\$ 13.91	\$ 41.73

Parts Total: \$ 41.73

93528 remove & disassemble 3rd brake light. solder in 3 bulbs. reassemble & install.

Misc Total: No Charge

Job # E Total \$ 550.53

Job # F Labor Total: \$ 376.20

BELL HOUSING/AIR CLEANER HOSES

Cause:

Correction(s):

C REPLACE BELL HOUSING HOSE AND OIL FILLER NECK

\$376.20

Tech Number: 29 Labor Type: CPP

Part Number	Part Description	Qty	List	
993-110-118-00	ANGLED HOSE	1	\$ 204.98	\$ 204.98
999-512-499-00	HOSE CLAMP	1	\$ 18.25	\$ 18.25
999-782-041-90	HOSE	1	\$ 54.42	\$ 54.42

Parts Total: \$ 277.65

* OEM means Original Equipment Manufacturer (factory) Parts | ** All parts are New unless specified otherwise.



PORSCHE

Paul Miller Porsche

3419 US46

Parsippany, New Jersey, 07054, US

Phone: 9732273000

Repair Order #: 124476
Tag #: T5234
Advisor: Mike Rose
Advisor No. #: 45
Order Open Date: 2023-08-07

93531 install missing hoses for clutch venting from bellhousing to air filter housing.

Misc Total: No Charge

Job # F Total \$ 653.85

Job # G Labor Total: \$ 0.00

OIL FILLER HOSE

Cause:

Correction(s):

CLINIC12 OIL FILLER HOSE

\$0.00

Tech Number: 29 Labor Type: CPP

Part Number	Part Description	Qty	List	Parts Total:	\$ 39.73
993-207-363-50	BELLOWS	1	\$ 39.73	\$ 39.73	

93528 installed missing oil filler neck hose.

Misc Total: No Charge

Job # G Total \$ 39.73

Job # H Labor Total: \$ 1,899.20

power steering rack

Cause:

Correction(s):

C REPLACE P/S RACK

\$1,699.20

Tech Number: 29 Labor Type: GPP

4WA PERFORM FOUR WHEEL ALIGNMENT

\$200.00

Tech Number: 29 Labor Type: CPTA

Part Number	Part Description	Qty	List	Parts Total:	\$ 7,329.58
993-347-011-X	STEERING GEAR	1	\$ 6,430.73	\$ 6,430.73	
PCG-419-831-C	BELLOWS	2	\$ 16.39	\$ 32.78	
993-347-325-01	STOP WASHER	2	\$ 59.95	\$ 119.90	
999-084-449-09	LOCK NUT	4	\$ 7.85	\$ 31.40	
000-043-305-74	PENTOSIN	1	\$ 40.39	\$ 40.39	

* OEM means Original Equipment Manufacturer (factory) Parts | ** All parts are New unless specified otherwise.



PORSCHE

Paul Miller Porsche

3419 US46

Parsippany, New Jersey, 07054, US

Phone: 9732273000

Repair Order #: 124476

Tag #: T5234

Advisor: Mike Rose

Advisor No. #: 45

Order Open Date: 2023-08-07

993-347-031-05	STEERING TRACK ROD	2	\$ 337.19	\$ 674.38
----------------	--------------------	---	-----------	-----------

93528 replace & bleed steering rack & tie rod assemblies complete. performed 4 wheel alignment.

Misc Total: No Charge

Job # H Total \$ 9,228.78

Job # I Labor Total: \$ 0.00

wiper blades

Cause:

Correction(s):

WB REPLACE WIPER BLADES

Tech Number: 29 Labor Type: CPP

\$0.00

Part Number	Part Description	Qty	List	Parts Total: \$ 100.05
993-628-901-01	1 SET: WIPER BLADES	1	\$ 100.05	\$ 100.05

93528 replaced wipers

Misc Total: No Charge

Job # I Total \$ 100.05

RO Comments

Amount Totals

Total Labor: \$ 6,273.20

Total Parts: \$ 8,534.72

Gas, Oil, Lube + Sublet + Misc: \$ 0.00

Sales Tax: \$ 982.69

* OEM means Original Equipment Manufacturer (factory) Parts | ** All parts are New unless specified otherwise.



PORSCHE

Paul Miller Porsche

3419 US46

Parsippany, New Jersey, 07054, US

Phone: 9732273000

Repair Order #: **124476**

Tag #: **T5234**

Advisor: **Mike Rose**

Advisor No. #: **45**

Order Open Date: **2023-08-07**

Shop Supplies:

\$ 25.00

Customer Total:

\$ 15,815.61

Terms and Acceptance

Customer acknowledges approval of work described in this Repair Order Summary. Any Warranties on the product sold herein are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express including any implied warranty of merchantability or fitness for a particular purpose. and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

Please look for a survey on your service experience. The manufactures survey will be sent to you by email. If you are not sure if your current email address is on file please check with your service advisor.

We're working hard to make customers for life!

Audit Trail

DOCUMENT ID f9db419f-2f10-4376-a7a7-dfd9cc7fc72e.pdf
STATUS SIGNED

Document History

CREATED 08:49:52 Aug-28-2023 PDT signature request with id [8080872] created using apikey [MGJiZWEwYmNiOWIwN2RkNjVkJWE1YmU0] from IP [54.174.160.138]. associated document id is [8080874].

SIGNED 08:49:52 Aug-28-2023 PDT document with id [8080874] associated with signature request with id [8080872] signed by IP [100.8.98.201]