

**NolaSport**  
 9700 Palm St.  
 New Orleans, LA 70118  
 (504) 301-2797

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. Storage fees begin 10 days after completion of repairs if payment is not made in full @ \$22.00 per day. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

**X** Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

**Invoice # A12981**

**2008 Porsche Boxster S** License #  
 Odom: 4836  
**VIN: WP0CB29898U731025** Color: Brown  
 Engine: H6 3.4L, 3387cc, Gas, FI Mfg. Date:  
 Trans: MANUAL Unit #  
 Inv Date: 6/06/2014  
 Service Writer: Linda Morgan  
 Status: Posted  
 Driver:  
 PO #  
 Key Tag / Hat #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Disc.	Ext
<b>Customer states that: Tire - check</b>						
Labor Service - Tires wearing normal and still have tread life present - No Concern present at this time. ED						0.00
<b>Customer states that: Tire pressure monitor light is appearing on dash</b>						
Labor Service - Client to repair ED						0.00
<b>Customer states that: Service</b>						
Labor Service - Perform annual sports car service with Cabin filter and air filter replacement. Change oil and filter, replace cabin filter, replace air filter, perform multi point inspection, top up all fluids, check/ adjust tire pressures, road test. Reset service interval indicator and stamp maintenance book ED					-46.00	276.00
New	997571219010	Cabin Filter	1.00	80.74		80.74
New	99610722553	oil cartridge	1.00	30.44		30.44
New	90012310630	drain plug seal	1.00	1.39		1.39
New	00033	Mobil One 0-40 Syn Oil	10.00	8.84		88.40
New	ZVW177901	Windshield washer solvent	1.00	8.69		8.69
New	99961110800	Battery - Remote	1.00	6.92		6.92
New	98711013300	Air Filter	1.00	54.00		54.00
Labor Service - Spark Plug replacement due by time - Remove and replace spark plugs, re-assemble vehicle, perform road test - vehicle operating as desinged at this time. ED					-28.00	168.00
New	99917022390	Spark Plug	6.00	27.62		165.72
Labor Service - Drive Belt Replacement due by time - Remove and replace drive belt, re-assemble vehicle, perform road test - vehicle operating as desinged at this time. ED					-24.00	144.00
New	99610215166	Drive belt	1.00	57.01		57.01
Labor Service - 2 yr. brake flush ED						110.00
New	00004320366	Brake Fluid-Super DOT4	1.00	31.50		31.50
Labor Service - Complimentary Wash & Vac						0.00
Labor Service - Complimentary 997 Turbo Loaner						0.00

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. Storage fees begin 10 days after completion of repairs if payment is not made in full @ \$22.00 per day. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

**NolaSport**  
 9700 Palm St.  
 New Orleans, LA 70118  
 (504) 301-2797

**X** \_\_\_\_\_  
 Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

**Invoice # A12981**

**2008 Porsche Boxster S**

License #

Inv Date: 6/06/2014

Continued from previous page

Posted 6/06/14 3:25PM

Visa 1,329.81

Invoice Summary

Parts 524.81  
 Labor 698.00

Sub Total 1,222.81  
 Sales Tax (LA) 107.00

**X** \_\_\_\_\_  
 Customer acknowledges receipt of merchandise and services.

Discard old parts

Original Estimate: 1,329.81

**Total 1,329.81**

**NolaSport**  
 9700 Palm St.  
 New Orleans, LA 70118  
 (504) 301-2797

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. Storage fees begin 10 days after completion of repairs if payment is not made in full @ \$22.00 per day. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

**X** \_\_\_\_\_  
 Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

**Invoice # A15255**

**2008 Porsche Boxster S**  
**VIN: WP0CB29898U731025**  
 Engine: H6 3.4L, 3387cc, Gas, FI  
 Trans: MANUAL

License #  
 Odom: 15745  
 Color: Brown  
 Mfg. Date:  
 Unit #

Inv Date: 7/28/2016  
 Service Writer:  
 Status: Posted  
 Driver:  
 PO #  
 Key Tag / Hat #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Ext
<b>Customer states that: The clutch pedal switch warning is coming on at times</b>					
	Labor Service - replace clutch pedal switch				28.00
	New 99761310902 Pedal Switch		1.00	36.14	36.14

Posted 7/28/16 4:34PM  
 Visa

70.39

**Invoice Summary**

Parts 36.14  
 Labor 28.00

Sub Total 64.14  
 Sales Tax (LA) 6.25

**X** \_\_\_\_\_  
 Customer acknowledges receipt of merchandise and services.



I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. Storage fees begin 10 days after completion of repairs if payment is not made in full @ \$22.00 per day. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

**NolaSport**  
 9700 Palm St.  
 New Orleans, LA 70118  
 (504) 301-2797

**X** \_\_\_\_\_  
 Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

**Invoice # A16039**

**2008 Porsche Boxster S**  
 VIN: WP0CB29898U731025  
 Engine: H6 3.4L, 3387cc, Gas, FI  
 Trans: MANUAL

License #  
 Odom: 18039  
 Color: Brown  
 Mfg. Date:  
 Unit #

Inv Date: 6/14/2017  
 Service Writer: Linda Morgan  
 Status: Posted  
 Driver:  
 PO #  
 Key Tag / Hat #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Disc.	Ext
<b>Customer states that: Maintenance Due</b>						
Labor Service - Perform annual sports car service. Change oil and filter, replace cabin filter, perform multi point inspection, top up all fluids, check/ adjust tire pressures, road test. Reset service interval indicator and stamp maintenance book RYAN					-41.60	249.60
New	99610722553	oil cartridge	1.00	28.62		28.62
New	90012310630	drain plug seal	1.00	1.64		1.64
New	00033	Mobil One 0-40 Syn Oil	10.00	9.03		90.30
New	ZVW177901	Windshield washer solvent	1.00	8.69		8.69
New	997571219010	Cabin Filter	1.00	78.55		78.55
Labor Service - 2 yr. brake flush RYAN						110.00
New	00004320366	Brake Fluid-Super DOT4	1.00	31.50		31.50
<b>Customer states that: Overall Inspection</b>						
Labor Service - Perform overall inspection during Annual Maintenance = No Charge RYAN						0.00
<b>Customer states that: Concern - hard wire in radar detector</b>						
Labor Service - Remove rear view mirror base for access, drill holes for radar mount. Remove driverside visor, driverside A pillar, remove over head light, and fuse box cover for access. Loosen fuse panel, hard wire into fuse panel with additional fuse behind all trim removed (Fuse C5 - purple fuse). Re-assemble vehicle and test operation = vehicle operating as designed at this time. RYAN					-40.00	240.00
<b>Customer states that: Top Concern - lubricate convertible top</b>						
Labor Service - Lubricate convertible top RYAN						0.00
Labor Service - Complimentary Wash & Vac RYAN						0.00
Labor Service - Complimentary GT2 NolaSport Loaner Vehicle						0.00
Labor Service - Complimentary vehicle pickup & delivery RYAN						0.00

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. Storage fees begin 10 days after completion of repairs if payment is not made in full @ \$22.00 per day. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

**NolaSport**  
 9700 Palm St.  
 New Orleans, LA 70118  
 (504) 301-2797

X \_\_\_\_\_

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

**Invoice # A16039**

**2008 Porsche Boxster S**

License #

Inv Date: 6/14/2017

Continued from previous page

Posted 6/16/17 1:25PM

Check (1836)

920.69

**Invoice Summary**

Parts 239.30

Labor 599.60

Sub Total 838.90

Sales Tax (LA) 81.79

X \_\_\_\_\_

Customer acknowledges receipt of merchandise and services.

Discard old parts

Original Estimate:

920.69

**Total**

**920.69**

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. Storage fees begin 10 days after completion of repairs if payment is not made in full @ \$22.00 per day. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

**NolaSport**  
 9700 Palm St.  
 New Orleans, LA 70118  
 (504) 301-2797

X \_\_\_\_\_  
 Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

**Invoice # A16941**

**2008 Porsche Boxster S**

License #  
 Odom: 19750  
 Color: Brown  
 Mfg. Date:

Inv Date: 8/15/2018

VIN: WP0CB29898U731025  
 Engine: H6 3.4L, 3387cc, Gas, FI  
 Trans: MANUAL

Unit #

Service Writer: Linda Morgan  
 Status: Posted  
 Driver:  
 PO #  
 Key Tag / Hat #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Disc.	Ext
------------------	----------------------	--------------------	-----	-------	-------	-----

Customer states that: **Maintenance Due**

Labor Service - Perform annual sports car Maintenance with engine air filter replacement. Replace engine oil and filter, replace engine air filter, perform multi point inspection, top up all fluids, check/ adjust tire pressures, road test. Reset service interval indicator and stamp maintenance book RYAN

-43.20 259.20

New 98711013301	Air Filter	1.00	52.57	52.57
New 99610722553	oil cartridge	1.00	26.12	26.12
New 00033	Mobil One 0-40 Syn Oil	10.00	9.03	90.30
New ZVW177901	Windshield washer solvent	1.00	8.69	8.69

Labor Service - Complimentary Wash & Vac DYL

0.00

Labor Service - Complimentary NolaSport GT2 Loaner Vehicle

0.00

Labor Service - Complimentary vehicle pickup & delivery

0.00

Posted 8/21/18 12:12PM

Check (1936) 477.08

Invoice Summary

Parts	177.68
Labor	259.20

Sub Total	436.88
Sales Tax (LA)	40.20

X \_\_\_\_\_  
 Customer acknowledges receipt of merchandise and services.



I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. Storage fees begin 10 days after completion of repairs if payment is not made in full @ \$22.00 per day. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

**NolaSport**  
 9700 Palm St.  
 New Orleans, LA 70118  
 (504) 301-2797

X

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

**Invoice # A20349**

**2008 Porsche Boxster S**

License #  
 Odom: 23290  
 Color: Brown  
 Mfg. Date:  
 Unit #

Inv Date: 9/26/2022  
 Service Writer: Linda Morgan  
 Status: Posted  
 Driver:  
 PO #  
 Key Tag / Hat #

VIN: WP0CB29898U731025  
 Engine: H6 3.4L, 3387cc, Gas, FI  
 Trans: MANUAL

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Ext
<b>Customer states that: Concern - Foam from AC vents, smoke from vents</b>					
Labor Service - Diagnose concern - found A/C pressure switch failing = replacement required. Remove and replace pressure switch, re-assmeble vehicle, perform evac & recharge, perform road and operation test = vehicle operating as desinged at this time. ANDREW					201.50
New	95561313703	A/C Pressure Switch	1.00	137.20	137.20
New	99970755541	O-Ring	1.00	3.56	3.56
Labor Service - Evac & Re-charge system. ANDREW					155.00
New	R134	refrigerant	2.00	16.24	32.48
New	R134D	Freon R134D W UV	1.00	23.90	23.90
<b>Customer states that: Top Concern - cable to canvas adjustment on passenger side</b>					
Labor Service - Repair right side Sublet TOP					0.00
		Top	1.00	62.00	62.00
<b>Customer states that: Maintenance Due</b>					
Labor Service - Perform Porsche Annual sportscar maintenance = Remove and replace engine oil and filter, check and adjust all tire pressures, top all fluid levels, clean all drains of leaves and debris, perform Porsche multi-point inspection, reassemble vehicle, reset maintenance interval indicator, stamp maintenance book, perform road and operation test = vehicle operating as designed at this time. ANDREW					229.40
New	99610722553	oil cartridge	1.00	27.84	27.84
New	00033	Mobil One Syn Oil	10.00	11.83	118.30
New	90012310630	drain plug seal	1.00	1.47	1.47
New	ZVW177901	Windshield washer solvent	1.00	8.69	8.69
<b>Customer states that: Brake Flush</b>					
Labor Service - 2 yr. brake flush ANDREW					178.50
New	00004320366	Brake Fluid-Super DOT4	1.00	31.50	31.50
<b>Customer states that: cup holder</b>					
Labor Service - Cup holder replacement required = Remove and repalce cup holder assembly and required trim ANDREW					139.50
New	997552294030	Cup Holder	1.00	422.19	422.19
New	99755239602V04	Hider	1.00	28.90	28.90
New	99755239801V04	Hider	1.00	102.71	102.71
New	99755239402V04	Hider	1.00	28.90	28.90
Labor Service - Complimentary Wash & Vac					0.00

**Warranties and Notices**

- 2 Years/ Unlimited Mileage

**NolaSport**  
 9700 Palm St.  
 New Orleans, LA 70118  
 (504) 301-2797

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. Storage fees begin 10 days after completion of repairs if payment is not made in full @ \$22.00 per day. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

**X** \_\_\_\_\_  
 Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

**Invoice # A20349**

**2008 Porsche Boxster S**

License #

Inv Date: 9/26/2022

Continued from previous page

Posted 10/06/22 1:19PM

Check (2264) 2,111.42

**Invoice Summary**

Parts	967.64
Labor	903.90
Sublet	62.00

Sub Total	1,933.54
Sales Tax (LA)	177.88

**X** \_\_\_\_\_  
 Customer acknowledges receipt of merchandise and services.



**NolaSport**  
 9700 Palm St.  
 New Orleans, LA 70118  
 (504) 301-2797

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. Storage fees begin 10 days after completion of repairs if payment is not made in full @ \$22.00 per day. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X \_\_\_\_\_  
 Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

**Invoice # A21923**

**2008 Porsche Boxster S**  
**VIN: WP0CB29898U731025**  
 Engine: H6 3.4L, 3387cc, Gas, FI  
 Trans: MANUAL

License #  
 Odom: 24119  
 Color: Brown  
 Mfg. Date:  
 Unit #

Inv Date: 6/26/2024  
 Service Writer: Linda Morgan  
 Status: Posted  
 Driver:  
 PO #  
 Key Tag / Hat #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Ext
<b>Customer states that: Maintenance Due</b>					
	Labor Service - Perform Porsche Annual sportscar maintenance = Remove and replace engine oil and filter, check and adjust all tire pressures, top all fluid levels, clean all drains of leaves and debris, perform Porsche multi-point inspection, reassemble vehicle, reset maintenance interval indicator, stamp maintenance book, perform road and operation test = vehicle operating as designed at this time. ANDREW				215.45
New	99610722553	oil cartridge	1.00	33.09	33.09
New	00033	Mobil One Syn Oil	10.00	11.83	118.30
New	ZVW177901	Windshield washer solvent	1.00	8.69	8.69
New	99961110800	Battery - Remote	1.00	8.59	8.59
Labor Service - Inspection reveals drive belt cracking = remove and repalce. ANDREW					
New	99610215166	Drive belt	1.00	74.30	74.30
Labor Service - 2 yr. brake flush ANDREW					
New	00004320366	Brake Fluid-Super DOT4	1.00	40.07	40.07

<b>Customer states that: 'Depress clutch pedal'</b>					
Labor Service - Diagnose concern - found clutch switch for speed control gummed up = replace. Replace clutch start interlock switch as well. ANDREW					232.70
New	99661311402	Switch	1.00	28.51	28.51
New	99761310950	Switch	1.00	49.41	49.41
Labor Service - Complimentary NolaSport Loaner Vehicle Provided					0.00

**Warranties and Notices**  
 • 2 Years/ Unlimited Mileage

X _____ Customer acknowledges receipt of merchandise and services.	Posted 6/28/24 4:48PM			<b>Invoice Summary</b>
	Check (1127)	1,245.66		Parts 360.96 Labor 779.75
				Sub Total 1,140.71 Sales Tax (LA) 104.95
			<b>Total</b>	<b>1,245.66</b>