



15553 Los Gatos Blvd.  
 Los Gatos, Ca 95032  
 P: 408-356-1515  
 F: 408-356-5057

CA BAR# ARD00257590  
 EPA #CAL00324798

brracing@gmail.com  
 www.brrperformance.com  
 BR Racing  
 BR\_Racing

## Authorization

Plate CA 3 VKK 241  
 Description Black 1996 Porsche 911 Carrera 4S H6 3.6L  
 3606CC VIN A  
 VIN WPOAA299XTS322832  
 Odometer 104,549 In / 104,552 Out

Appointment 2/14/2024 10:47 AM  
 Promised 2/14/2024 10:47 AM

### Concern

#### (1) Notes

The customer would like to bring in their car for the following services: (1) customer would like a PPI (pre-purchase inspection) performed

### Inspection

#### PPI Inspection

Inspection - PPI (Pre-purchase Inspection) - includes full multi-point visual inspection, run full diagnostic check / report, check service indicator, check readiness and road test - does not include a compression / leak down test (Note - if a Porsche, also run engine hour / over-rev report). BRacing makes no representation as to the readiness, safety, engine reliability, cooling system, suspension reliability, or reliability of any part, system, subsystem, module relative to the car being inspected. If issues are present, BRacing is not diagnosing, or providing any guidance on repairs, solutions, needs, or concerns.

Labor

\$250.00  
 Sub            \$250.00

#### Notes:

See full inspection report for all items reviewed. Key items to note: During Inspection of vehicle found the following items, During test drive found the steering wheel to be off centered, found the tires to have signs of weather cracking, and inner edge wear due to too much camber on vehicle. Found Front and rear outer axle boots to be throwing grease, and found the inner boots to be attached with zip ties. Found both Front wheels to have slight bearing play, Severity level 1, on scale of 1 to 3. Slight Seepage coming from possible push rod tubes. (Severity Level 1, on scale of 1 to 3)

### Service

#### Tire Pressure

Tire Pressure In (PSI):.....Tire Pressure Out (PSI):.....Brake Pad Measurement (MM):.....Tire Tread Depths (32nd's):  
 32\_LF | 30\_RF.....36\_LF | 36\_RF..... 8\_LF | 8\_RF..... 3\_LF | 3\_RF  
 34\_LR | 35\_RR .....44\_LR | 44\_RR..... 9\_LR | 9\_RR..... 4\_LR | 3\_RR

Total Parts	\$0.00
Total Labor	\$250.00
Total Before Taxes & Miscellaneous Charges	<u>\$250.00</u>
<b>Grand Total</b>	<b><u>\$250.00</u></b>

I hereby authorize the repairs to be done along with the required materials and agree that you are not responsible for loss or damage to the vehicle or contents in the case of fire or theft or causes beyond your control. I hereby grant you and your employees' permission to operate the vehicle on the streets and highways or elsewhere for the purpose of testing and or inspection. I acknowledge my indebtedness for the amount of this invoice and acknowledge and agree that in the event of non-payment that the repairer is entitled to liens under any available Repair Liens or Storage Liens Legislation. This information and any other information we have in our data base is restricted to authorized personnel only. This information will be used solely for the current and future service of your vehicle, warranty registration, and any other use required by law. You have a right to a written estimate. A repairer may not charge an amount that is more than ten (10) per cent above that estimate. If you waived your right to an estimate, the repairer must have your authorization of

the maximum amount that you will pay for the repairs. The repairer may not charge more than the maximum amount you authorized. In either case, the repairer may not charge for any work you did not authorize.

**Customer Signature:** \_\_\_\_\_

**Alingh, Ben - 3 VKK 241 CA - 1996 Porsche 911 Carrera 4S [WP0AA299XTS322832]**

**PPI Inspection**

Inspection - PPI (Pre-purchase Inspection) - includes full multi-point visual inspection, run full diagnostic check / report, check service indicator, check readiness and road test - does not include a compression / leak down test (Note - if a Porsche, also run engine hour / over-rev report). BRacing makes no representation as to the readiness, safety, engine reliability, cooling system, suspension reliability, or reliability of any part, system, subsystem, module relative to the car being inspected. If issues are present, BRacing is not diagnosing, or providing any guidance on repairs, solutions, needs, or concerns.

PPI Inspection	O	S	R
<b>Accessories</b>			
Horn(s)			
Release Cable: Hood, Hatch, Trunk, Fuel Door			
Lift Support(s): Hood, Hatch, Trunk			
Power Windows / Power Door Locks / Power Seat			
Cruise Control			
Wiper			Front- ok
Washer Fluid / Reservoir / Pump / Nozzles / Hoses (Front / Rear)			
Speedometer / Tachometer			
Dash Gauges / Indicator Lights			
Rear Defroster			
Seat Belts			
Mirrors (Rear View / Side)			
Fuses / Fuseable Link			
Switches / Relays			
Other:			
<b>Electrical</b>			
Exterior Lights (Front / Rear / Side / Turn)			
Flasher (Turn / Hazard)			
Interior Lights (Instrument / Courtesy / Warning)			
Fuse / Fuseable Link			
Switches / Relays			
Battery / Battery Test / Cables / Cable Connections			Battery is good 806CCA Starter good 10.9V Alternator good 13.47V
Alternator / Starter			
DRIVE / SERPENTINE BELT & Belt Tensioner			
Other:			
<b>Cooling</b>			
Anti-Freeze / Coolant			N/A
Coolant Overflow Reservoir / Cap / Lines			
Radiator / Cap			
<b>COOLING SYSTEM HOSES</b>			
Water Pump / Thermostat			
Fan / Fan Clutch			
Electric Fan / Auxiliary			
Fuses / Fuseable Link			
Switches / Relays			
Freeze / Frost Plug(s)			
Block Heater / Cord			
Other:			
<b>HVAC (Heating, Ventilation &amp; Air Conditioning)</b>			

PPI Inspection	O	S	R	
PERFORMANCE TEST A/C	<input checked="" type="checkbox"/>			Blowing at 54 degrees, Outside Temp 65 degrees, recharge system for better cooling
CABIN AIR FILTER Condition				
Blower Motor / Switch / Relay / Resistor	<input checked="" type="checkbox"/>			
AC Hoses	<input checked="" type="checkbox"/>			
Compressor / Clutch / Coil	<input checked="" type="checkbox"/>			
Evaporator / Condensor				
Automatic Temperature Control (ATC)				
Heater Hoses				
Other:				
<b>Driveability (Fuel, Ignition, Emissions)</b>				
CEC / Service Soon Light	<input checked="" type="checkbox"/>			
Computer System Scan	<input checked="" type="checkbox"/>			
MAINTENANCE TUNE-UP Status				
AIR FILTER Condition				
SPARK PLUGS / PLUG WIRES				
Coil / Boot / Insulator				
Distributor / Cap / Rotor				
FUEL FILTER				
FUEL INJECTION FLUSH				
Fuel Tank / Lines / Hoses / Fittings	<input checked="" type="checkbox"/>			
Other:				
<b>Suspension &amp; Steering</b>				
Ball Joints (Upper / Lower)	<input checked="" type="checkbox"/>			
Control Arms (Upper / Lower)	<input checked="" type="checkbox"/>			
Tire Rod Ends (Inner / Outer)	<input checked="" type="checkbox"/>			
Pitman Arm / Idler Arm				
Steering Gear / Rack & Pinion	<input checked="" type="checkbox"/>			
Power Steering Pump / Hoses	<input checked="" type="checkbox"/>			
POWER STEERING FLUID FLUSH				
STRUTS (Front / Rear)	<input checked="" type="checkbox"/>			
SHOCKS (Front / Rear)	<input checked="" type="checkbox"/>			
Springs (Front / Rear)	<input checked="" type="checkbox"/>			
WHEEL ALIGNMENT				Steering wheel is slightly off to the left
Other:				
<b>Tires &amp; Wheels</b>				
Tires				Size:
Tire Condition & Tread Depth		<input checked="" type="checkbox"/>		_3_/32"LF, _3_/32"RF 2006 Major cracks on the outer, front tires have excessive wear on the inside edge, too much camber 4_/32"LR, _3_/32"RR 2010
Wheels / Rims	<input checked="" type="checkbox"/>			
Other:				
<b>Brakes</b>				
Disc Brake Pad	<input checked="" type="checkbox"/>			Front: _/32"   _40_/1%   _8_/MM Rear: _/32"   _50_/1%   _9_/MM
Disc Brake Rotor	<input checked="" type="checkbox"/>			Front: small lip Rear: small lip
Drum Brake Shoe				
Brake Drum				
Brake / Caliper Hardware (Front / Rear)	<input checked="" type="checkbox"/>			
Brake Calipers (Front / Rear)	<input checked="" type="checkbox"/>			
Master Cylinder / Power Brake Booster	<input checked="" type="checkbox"/>			
Brake Hoses / Lines	<input checked="" type="checkbox"/>			
Brake Cables				

FPI Inspection	O	S	R	
BRAKE FLUID Condition	<input checked="" type="checkbox"/>			cc LEVEL 40 blue ate fluid good
Parking Brake	<input checked="" type="checkbox"/>			
Other:				
Drive Train				
Drive Shaft / Universal Joint(s) / Center Support				
CV Joint / Boot / Axle Shaft			<input checked="" type="checkbox"/>	Front driver and passanger outter cv boots throwing grease Front inner cv boots clamped down using zip ties Rear Driver outter boot throwing grease Also rear inner boots clamped down using zip ties
Pinion / Axle Seal(s)				
Bearings				Both front wheels have wheel bearing play Level 1
DIFFERENTIAL Leaks / Fluid	<input checked="" type="checkbox"/>			
Other:				
Engine				
Valve Cover / Intake / Cylinder Head Gasket	<input checked="" type="checkbox"/>			
Oil Pan / Drain Plug / Gaskets	<input checked="" type="checkbox"/>			
Front Main / Rear Main Seals	<input checked="" type="checkbox"/>			
Timing Chain / Gears				
TIMING BELT				All 3 belts are in good condition
Motor Mounts / Torque Strap	<input checked="" type="checkbox"/>			
VALVE ADJUSTMENT				
Bearings	<input checked="" type="checkbox"/>			
Engine Hour / Over-Rev Report				Porsche Only
Other:				engine push rod tubes seeping (severity level 1)
Transmission & Clutch				
TRANSMISSION FLUID / Leaks				
Seals (Front / Rear / Shift / Speedometer)	<input checked="" type="checkbox"/>			
Shifter / Linkage / Cable	<input checked="" type="checkbox"/>			
Clutch Disc / Pressure Plate / Release Bearing / Fork	<input checked="" type="checkbox"/>			
Clutch Cable / Linkage / Adjustment	<input checked="" type="checkbox"/>			
Clutch Master Cylinder / Slave Cylinder	<input checked="" type="checkbox"/>			
Transfer Case / Shifter	<input checked="" type="checkbox"/>			
Transmission Mount(s)	<input checked="" type="checkbox"/>			
Other:				
Exhaust				
Catalytic Converter	<input checked="" type="checkbox"/>			
Muffler / Resonator	<input checked="" type="checkbox"/>			
Exhaust pipe	<input checked="" type="checkbox"/>			
Manifold / Gasket	<input checked="" type="checkbox"/>			
Clamps / Hangers	<input checked="" type="checkbox"/>			
Other:				
Additional Notes & Observations:				